



## High Load Ultran® - Less than 6 inch Stroke Lengths

Orders for the High Load Ultran® in stroke lengths of six (6) inches or less require application review. Units with less than six (6) inches of stroke reduce the life of the ball bearings. The reduced life results because the ball bearings do not get re-circulated properly, distributing the load among the same bearing points continuously.

These applications will be done as a special.

The information presented is in Bimba's best engineering opinion and should be used for reference only. Recommendations derived should be verified under actual operating conditions. Bimba reserves the right to change specifications without prior notice.

**Bimba Manufacturing Company**  
Monee, IL 60449-0068  
Telephone: 708.534.8544  
Email: [cs@bimba.com](mailto:cs@bimba.com)  
[www.bimba.com](http://www.bimba.com)  
Rev Level: 0

Leaders in Actuation.

To learn more about this product, scan this QR code with your mobile device.

